



ROTAX
NEW AGE KARTING


BRP

CUSTOMER INFO 2011 11 08

**EXCHANGE CAMPAIGN COIL 265571 (Coil with extension wire)
ALL ROTAX 125 MAX ENGINES**

Dear Customer,

Unfortunately, BRP-Powertrain noticed that rumours on the market concerning Rotax 265571 "extension wire"- coils have been increasing.



To cure this situation BRP-Powertrain has decided that the ignition coils with extension wire will no more be valid within the ROTAX MAX Challenge regulations 2012 (valid as of January 01st, 2012) for all engine classes (125 Micro MAX, 125 Mini MAX, 125 Junior MAX and 125 MAX).

To support customers which have an ignition coil with extension, BRP-Powertrain offers an exchange campaign for these ignition coils.

Within the defined time frame of December 1st 2011 until April, 30th 2012 customers can return their ignition coils (marked with the number "265 571" on the housing) to their ROTAX service centers/dealers which will exchange the ignition coil exchanged **free of charge** by a new ignition coil.

PLEASE NOTE: 265 578 does not include a spark plug cap!

Time frame: December 01st, 2011 until April 30th, 2012.
Conditions: Exchange free of charge

Best regards,

BRP-Powertrain